

Appendix B: 20 Mile Creek Restoration Project Photos



PHOTO 1. OLD RAILROAD GRADE AND REMNANT CULVERT AT 20 MILE CREEK



PHOTO 2. TAILWATER CONTROL AND BRAIDED CHANNEL BELOW OLD CROSSING

Appendix B: 20 Mile Creek Restoration Project Photos



PHOTO 3. BRAIDED, OVER-STEEPENED CHANNEL BELOW OLD CROSSING AT 20 MILE CREEK






PHOTO 4. LOWER END OF PLUNGE POOL, TAILWATER CONTROL AND BRAIDED CHANNEL

Appendix B: 20 Mile Creek Restoration Project Photos



5. TOP LEFT: UPSTREAM OF REMNANT CULVERT

6. TOP RIGHT: DOWNSTREAM REMNANT CULVERT

7. LOWER LEFT: 20 MILE CREEK BELOW CULVERT

8. LOWER RIGHT: 20 MILE CREEK BELOW CULVERT